
**SCIENTECH<sup>®</sup>** 

**Series 12000** 

**Electronic Balance** 

Setup and Operating Procedures



Thank you for choosing a Scientech Electronic Balance. Scientech, an ISO9001 registered company, and its employees are pleased to provide you with a balance designed and manufactured for years of reliable service and proudly made in the U.S.A. The attractive quality of Scientech balances has been demonstrated by being certified to carry the "CE" mark of conformity.


Please read this manual completely before using your balance. This information will enable you to fully utilize your balance and should be located nearby to be used as a quick reference guide. The balance is intended to be used only in the manner outlined in this manual. Misuse of the balance may cause product failure.

# **Table of Contents:**

Unpacking and Setup:	3
Choose the Proper Environment:	3
Level the Balance:	4
Unlock the Clamping Screw:	4
Connect to an Electrical Outlet:	
Turn the balance on:	
Good Measurement Practices:	
Equipment:	
Environment:	
Operator:	
Front Panel Controls:	
The ON/OFF (I/O) Button:	
The RANGE/FUNCTION Button:	
Single Range Balance Models:	
Dual Range Balance Models:	
The MODE Button:	
The MODE Button:	
The ZERO Buttons:	
Balance Functions and Features:	
Autocalibration – To Calibrate the balance to an External Weight:	
Autocalibration – To Calibrate the Balance to a Motorized Internal Weight:	
Autocalibration – To Calibrate the Balance and its Motorized Internal Calibration Weight to an External Weight:	
RS-232 Command for CAL 1 Using the Internal Weight:	
(CAL 2) Linearity:	
(PCS) Front Panel Parts Counting:	
(HI-OK-LO) Checkweighing / Process Control Limits:	10
(%) Percent Weighing:	11
$(\overline{T})$ Live Animal Weighing / Severe Environment Weighing:	11
Floating Tare <sup>™</sup> (dual range models only):	
Capacity Tracker:	
Selectable Filters, Stability Indicator, and Send-When-Stable:	
Density Determination:	
Below Balance Weighing:	
Specific Gravity Determination:	
Security Bracket:	
Options:	
Optional RS-232 Printers:	
RS-232 Interface:	
RS-232 Specifications:	
RS-232 Specifications. RS-232 Front Panel Configuration:	
Using Bi-Directional Communications:	
Bi-Directional RS-232 Command Set:	
Type 2 Commands – Balance Input Functions:	
Type 3 Commands – Balance Output Functions:	
Type 4 Commands – Clock/Calendar Functions:	
RS-232 Balance Message Formats:	
Format A - Balance in the normal weighing mode:	
Format A - Balance in a special weighing mode:	
Format B - Balance in normal weighing mode:	
Format B - Balance in a special weighing mode:	
Format C:	
Bi-Directional RS-232 Error Messages:	
Troubleshooting Guide:	
Environmental Requirements:	22

# **Unpacking and Setup:**

The balance, weighing pans, remote power supply, windscreen (standard on some models) and any optional accessories are packed in a foam support to protect them from shock during shipping and handling. Save and reuse all packing material for future damage-free shipments.




### **Choose the Proper Environment:**

The environment in which your balance is used is very important. Air movement, temperature changes, vibrations, direct sunlight, etc. influences the performance of high precision balances. Therefore, place your balance on a solid, sturdy surface that is free of air currents and vibration and not in direct sunlight. The surface should not be magnetic and should be located away from doors, windows, heaters, air conditioners and fans.

### Level the Balance:

Turn the FRONT FEET as shown in Figure 2 to level the balance by centering the bubble in the LEVEL INDICATOR which is shown in Figure 1. Turning the foot, as shown below, raises that side of the balance and an opposite adjustment lowers it. When properly adjusted the metal center shaft of the assembly will protrude from the center of the plastic foot and will contact the working surface to support the balance. The plastic foot will be raised up against the bottom of the balance and will not be touching the weighing table.



### **Unlock the Clamping Screw:**

All balances are equipped with a special clamping screw that locks the balance suspension during shipping. This screw must be loosened before the balance can be operated (see Figure 3).

- 1. Locate the black knob, on the front center of the balance, underneath the display area.
- 2. Remove the paper tag.
- 3. Turn the knob, in the direction shown below, until finger tight.

If the balance is ever shipped or moved long distances, the damping screw should be retightened by turning the knob in the opposite direction until finger tight.




Figure 3 Unlocking Clamping Screw

### **Connect to an Electrical Outlet:**

The balance is supplied with a 115/220, 50/60 Hz automatic switching, remote power supply. This power supply will work with most electrical outlets, however, before making any connections, verify that the power (VAC) requirement shown on the remote power supply is compatible with the AC power outlet to which the balance will be connected.

Note: First plug the round DIN connector into the balance's rear panel receptacle. Then, plug the power supply into a grounded AC outlet.

Note: Do not alter or bypass the ground plug in any way. Doing so adversely affects the performance of the balance.
Note: Scientech recommends that the balance be plugged into an electrical outlet at all times. This insures the balance is always warmed up and ready for use.

#### Turn the balance on:

Press the ON/OFF button one time to turn the balance on and observe the following turn on sequence.




Figure 4 Turn On sequence

Allow the balance to warm up for at least 1 hour, then follow the Autocalibration instructions to calibrate the balance.

# **Good Measurement Practices:**

(As quoted from the Mass Standards Handbook by Troemner, 3-015BKT rev 1/03)

There are numerous steps that one can take in order to improve the quality of a mass measurement system. However, they usually fall within three main categories: the equipment, the environment, and the operator. If even one of these areas is neglected, it can have a dramatic negative impact on your results. Although these suggestions are not meant to be all encompassing or all-inclusive, the improvements that can be made following these simple guidelines are extraordinary.

#### **Equipment:**

- 1. Select weights that have a tolerance that is one third or better than the accuracy you require for your application. This way the error of the weight will not dramatically impact the quality of your measurements.
- 2. The equipment must be of sufficient readability to calibrate or measure the weight or sample under test.
- 3. The balance should be placed on a stable platform free from the effects of vibration. The most common type of setup involves placing the instrument onto a balance table that is constructed of marble or granite.
- 4. Never use a balance or scale as soon as it is turned on (plugged in). The internal electronic components need to stabilize and "warm up" for at least 24 hours once the equipment has been energized. Troemner recommends that you leave this instrument plugged in twenty four hours a day, seven days a week.
- 5. Never use a balance that has been idle for several hours without first "exercising it" and calibrating it. A balance is exercised by repeatedly placing and removing weights from the balance pan. We recommend that this be done at least ten times each with a weight that is 100% of the max capacity of the balance. After exercising, the balance should be calibrated. If these two techniques are consistently employed, a noticeable improvement will result in both linearity and stability of the measurement.
- 6. When weights are not in use, store them in the case in which they were supplied. If the weights were not supplied with a case, either purchase a case or use a clean container to protect the surfaces. This will keep airborne particles from getting on your weights between uses. Weights should be in thermal equilibrium with the balance so store weights near your balance. Another option is to leave calibration masses commonly used inside the weighing chamber when not in use. This assures your weights are in thermal equilibrium with the balance producing a better measurement.

#### **Environment:**

- 1. The more stable your environment, the better your measurement results. Changes in temperature, pressure, and humidity affect balance performance and weight stability. Ideal room conditions are 20° C with a relative humidity between 45% and 60%. Fluctuations in temperature should not exceed 1° C per hour. Humidity fluctuations should not exceed 10% per hour.
- 2. Balances should not be placed in close proximity to anything that shakes, vibrates, or stirs violently. Avoid placing your equipment near centrifuges, vortexers, or shakers.
- 3. Do not place your balance and/or scale near anything that generates heat. Heat will cause the balance chamber to warm and due

to the effects of the thermal expansion introduce large errors into your measurement. Do not place the balance near a window. Sunlight can penetrate the window, warm the balance chamber at different rates during the day, and affect the quality of your work.

- 4. Avoid placing the balance near sources of drafts, extreme air currents, or near air-conditioning vents. These positions can cause your readings to be unstable and can dramatically cool the balance chamber when the air-conditioning system begins to run.
- 5. The measurement environment should be clean and free of excessive contaminants. Contaminants such as dirt and grease can adversely affect the weight of an object.

### **Operator:**

- 1. Never touch a weight with your bare hands. Oils and contaminants from your hand will be transferred to the weight and introduce a significant error. It is recommended that all weights be manipulated with gloved hands or forceps. The two types of gloves that are commonly used and accepted are either latex (powderless) or cotton. Avoid any metal to metal contact when handling or storing weights. This will cause scratches that may introduce error. All weight forceps and weight lifters should be either nonmetallic (plastic or wood) or if metal, covered with a soft protective coating or material to avoid scratches.
- 2. Place the weight or sample near the center of the balance pan. A small offset from center can have a pronounced effect and introduce undue variation.
- 3. Take special care not to breathe onto the weight or into the balance chamber. Back away from the instrument. This will prevent any thermal transfer of heat from your breath or body to the balance, the weight, or the sample.
- 4. Time your measurements. Consistent sample times will provide more consistent measurement.

# **Front Panel Controls:**




Figure 5 - Balance Front Panel

# Note: The annunciators CNV, S and $\overline{X}$ are shown in Figure 5, but are not available through any front panel controls. However, these functions along with all other front panel functions are available through RS-232 commands. These commands are discussed later in the RS-232 section of the manual.

#### The ON/OFF (I/O) Button:

When the balance is off, pressing the ON/OFF button will start the turn on sequence shown in Figure 4. During this sequence the balance is doing an automatic systems checkout to insure it is functioning properly.

If your balance was purchased with the optional motorized internal calibration weight, all objects on the stainless steel pan must be removed before turning on the balance using the front panel ON/OFF switch. Press the ON/OFF button and observe the turn on sequence shown in Figure 4. With the motorized internal calibration weight installed, the balance will then load the internal weight on and off the weighing sensor in order for the internal weight to be positioned correctly. Please wait until all weight readings have stopped changing, the "OK" annunciator appears, and the motor is silent before zeroing the balance and starting weighing operations.

When the balance is on, pressing the ON/OFF button will turn off the display.

### The RANGE/FUNCTION Button:

#### **Single Range Balance Models:**

Pressing the RANGE/FUNCTION button begins the following menus cycle:

- PCS Front panel parts counting
- HI OK LO Checkweighing
- CAL 1 Autocalibration
- CAL 2 Linearity
- $\overline{T}$  Live animal weighing
- % percent weighing

To select the desired function, press the MODE button when it appears on the display.

#### Note: Front panel parts counting is not available with bi-directional RS-232 enabled.

#### **Dual Range Balance Models:**

Pressing the RANGE/FUNCTION button allows you to choose from low (LO), high (HI) and autorange (HI LO). As a range is selected its annunciator briefly appears at the upper right of the display. Autorange automatically switches from low range to high range when a weighing exceeds the capacity of the low range.

# Note: On dual range balance models, pressing the RANGE/FUNCTION and MODE buttons simultaneously will duplicate the menu described for single range balances.

#### The MODE Button:

For all models, except the SM models, pressing the MODE button starts the unit of weight cycle as follows: grams(g), carats(ct), pennyweights(dwt), troy ounces(ozt), ounces(oz), pounds(lb), kilograms(kg) and milligrams(mg). When the desired unit of weight appears, press the MODE button a second time to select that unit of weight.

The available units of measurement for SM models are grams (g) and milligrams (mg).

An optional, factory installed, user specified, custom unit of measure is available. If you have this special unit of measure feature in your balance, (A) appears in the unit of weight cycle in addition to the other options. Press the MODE button to select this option.

#### **The SEND Button:**

Pressing the SEND button sends the information on the balance's display to an external device via the RS-232 interface.

Note: Scientech balances are DTE (computer) devices. If communicating to another DTE device (ie computer), a Scientech RS-232 cable, PN10697, or normal null modem cable is required. If you are communicating to a DCE device (printer), a serial cable is required. Scientech offers a serial cable, PN11367, for your convenience.

You may send the time and date along with the weight reading when you press the SEND button or you may send weight readings automatically at user specified time periods (see the Bi-directional RS-232 Command Set, Type 4 Commands section for details). Weight readings may also be sent to a computer or printer continuously every 200 milliseconds (see the RS-232 Front Panel Configuration section for details). Weight readings may be sent automatically when the balance reaches stability (see Selectable Filters section).

#### The ZERO Buttons:

There are two (2) ZERO buttons. Pressing either button at any time returns the display to zeros. When a weighing that has been zeroed out is removed from the weighing pan, a negative reading is displayed. To return the display to zeros, press one of the ZERO buttons.

# **Balance Functions and Features:**

### Autocalibration – To Calibrate the balance to an External Weight:

This procedure calibrates your balance to an external calibration weight. If your balance has a motorized internal calibration weight (9000-INT), please use the procedure for Autocalibration Using 9000-INT Motorized Internal Calibration Weight.

- Note: Dual range models must be placed in HI range before starting the calibration procedure.
- Note: For correct calibration weight refer to specification charts in the back of the manual.
- Note: The balance should be warmed up for at least one (1) hour prior to calibration and leveled according to the Unpacking and Setup section.
- Note: Perform autocalibration every time you move your balance.

Calibrate the balance using a recently certified external calibration weight. Metrology handbooks state that the calibration weight utilized to calibrate a balance should have a tolerance no larger than the readability of the balance divided by 3. Therefore, SM models need a  $\pm 0.0033$ mg tolerance weight or better, SA models need a  $\pm 0.033$ mg tolerance weight or better, SL models need a  $\pm 3.3$ mg tolerance weight or better, and SG models need a  $\pm 3.3$ mg tolerance weight or better. In addition, these same handbooks recommend that all balances be calibrated using an external certified calibration weight even if the balance has an internal calibration weight.

	User Action	Balance Response
1	Remove any containers or weighing samples	Zeros are displayed
	so that nothing is on the weighing pan, then	
	press the ZERO button	
2	Press the RANGE/FUNCTION button (or	Balance display cycles repeatedly through PCS, HI OK LO, CAL 1, CAL 2,
	MODE and RANGE buttons simultaneously	$\overline{T}$ and %.
	for dual range balance models)	
3	Press the MODE button when CAL 1 appears	CAL 1 and a flashing 0 are displayed.
4	Wait 10 seconds for the balance to stabilize,	The display stops flashing, CAL 1 and a solid 0 are displayed. In
	then press the ZERO button.	approximately 15 seconds, when this step is complete, a single weight or two
		alternating weights will begin flashing on the display.
5	Place one of the flashing weights on the	The display stops flashing, CAL 1 and the selected weight are displayed.
	balance's weighing pan.	
6	Wait 10 seconds for the balance to stabilize,	The display will momentarily blink, then the selected weight will continue to be
	then press the ZERO button.	displayed. In approximately 15 seconds, when this step is complete, the display
	Do not remove the weight from the pan.	will blank, flash "OK", then display the calibration weight including decimal
		places. The balance is now calibrated and in the normal weighing mode.
7	Remove the calibration weight.	The display returns to zeros.

### Autocalibration – To Calibrate the Balance to a Motorized Internal Weight:

This procedure is only for SA and SM balances with the suffix IW after the model number which means a motorized internal calibration weight is installed.

Note: Dual range models must be placed in HI range before starting the calibration procedure.

Note: For correct calibration weight refer to specification charts in the back of the manual.

# Note: The balance should be warmed up for at least one (1) hour prior to calibration and leveled according to the Unpacking and Setup section.

	User Action	Balance Response
1	Remove any containers or weighing samples	Zeros are displayed.
	so that nothing is on the stainless steel pan.	
	Then press the ZERO button.	
2		Display cycles repeatedly through PCS, HI-OK-LO, CAL1, CAL2, $\overline{T}$ , and %.
	RANGE buttons simultaneously for dual	
	range models).	
3	Press the MODE button when CAL1 appears.	CAL1 and a flashing 0 are displayed.
4	Wait 10 seconds. Then press the MODE	The display shows a flashing CAL. This means that the automatic calibration
	button.	procedure using the internal weight has begun. The procedure will take about 30
		to 90 seconds. When the procedure is complete, the display will blank and then
		return to its normal weighing mode. This means that your balance is now
		calibrated. If the calibration cannot be completed due to air currents, an unstable
		environment (vibration), an incorrect weight, or any other reason; a brief "ERR"
		message will appear on the display and the balance will return to Step 3.

## Autocalibration – To Calibrate the Balance and its Motorized Internal Calibration Weight to an External Weight:

This procedure is only for SA and SM balances with the suffix IW after the model number, which means a motorized internal calibration weight is installed. This procedure first calibrates the balance to an external calibration weight then recalibrates the internal calibration weight to the external weight. This procedure can also be used to only calibrate the balance to the external weight without recalibrating the internal calibration weight.

- Note: Dual range models must be placed in HI range before starting the calibration procedure.
- Note: For correct calibration weight refer to specification charts in the back of the manual.
- Note: The balance should be warmed up for at least one (1) hour prior to calibration and leveled according to the Unpacking and Setup section.
- Note: Perform autocalibration every time you move your balance.

Calibrate the balance using a recently certified external calibration weight. Metrology handbooks state that the calibration weight utilized to calibrate a balance should have a tolerance no larger than the readability of the balance divided by 3. Therefore, SM models need a  $\pm 0.0033$ mg tolerance weight or better, SA models need a  $\pm 0.033$ mg tolerance weight or better.

	User Action	Balance Response
1	Remove any containers or weighing samples so that nothing is on the weighing pan, then press the ZERO button	Zeros are displayed
2	Press the RANGE/FUNCTION button (or MODE and RANGE buttons simultaneously for dual range balance models)	Balance display cycles repeatedly through PCS, HI OK LO, CAL 1, CAL 2, $\overline{T}$ and %.
3	Press the MODE button when CAL 1 appears	CAL 1 and a flashing 0 are displayed.
4	Wait 10 seconds for the balance to stabilize, then press the ZERO button.	The display stops flashing, CAL 1 and a solid 0 are displayed. In approximately 15 seconds, when this step is complete, a single weight or two alternating weights will begin flashing on the display.
5	Place one of the flashing weights on the balance's weighing pan.	The display stops flashing and the selected weight is displayed.
6	Wait 10 seconds for the balance to stabilize, then press the ZERO button. <b>Do not remove the weight from the pan.</b>	The display will momentarily blink, then the selected weight will continue to be displayed. In approximately 15 seconds, when this step is complete, the display will blank, flash "OK", then shows CAL 1 and a flashing 0.
7	To continue and recalibrate the internal calibration weight, proceed to step 8. To stop here without calibrating the internal calibration weight, remove the calibration weight from the weighing pan and press the MODE button.	The balance has been calibrated and the display returns to zeros.
8	Remove the calibration weight from the weighing pan, then press the ZERO button.	The display shows a flashing CAL and the internal weight recalibration begins. You will hear the internal motor and see the capacity tracker fill and then empty. The procedure will take about 30 to 90 seconds. When complete, the display will blank and then return to its normal weighing mode. The balance is now calibrated to the external weight and the internal weight is calibrated to the external calibration weight.

## **RS-232** Command for CAL 1 Using the Internal Weight:

To initiate a CAL 1 using the motor driven internal calibration weight via a RS-232 command, issue the command ACAL[CR]. The automatic internal weight calibration will begin immediately without further user interaction. For a more complete discussion about RS-232, please see the Bi-directional RS-232 Command Set section.

## (CAL 2) Linearity:

Linearity is set in the balance's software at the factory during the manufacturing process. It requires a special set of weights that are not available commercially. When a CAL 1 function is performed the linearity is automatically reset as well. Unless the balance is damaged the linearity will not change. Therefore, CAL 2 should never be performed by the user.

### (PCS) Front Panel Parts Counting:

Note: Access to the PCS function via the front panel is disallowed if bi-directional RS-232 is enabled. RS-232 is enabled by selecting local control (LC) oFF (see RS-232 Front Panel Configuration section for details). Local control ON means the front panel controls the balance.

	User Action	Balance Response	
1	Press the FUNCTION button (or MODE and RANGE buttons simultaneously for dual range models).	Display cycles repeatedly through PCS, HI-OK-LO, CAL1, CAL2, $\overline{T}$ , and %.	
2	Press the MODE button when PCS appears on the display.	PCS and 0 flash. This is a prompt to zero the balance with the container that will hold the pieces on the weighing pan.	
3	Place the empty container on the pan, wait 10 seconds, and then press the ZERO button.	PCS and 10 flash. This is a prompt to place 10 pieces in the container.	
4	Place 10 pieces in the container, wait 10 seconds, and then press the ZERO button.	PCS continues to flash and OK appears on the display while a stable weight is obtained. Then 10.000, or something very near it, appears on the display. The number of decimal places depends on the weight. PCS continues to flash. This prompts you that you may now increase the sample size in order to obtain a more statistical significant sample which yields a more accurate parts counting conversion factor. The decimal places aid you in rounding the piece count correctly as the sample size increases.	
5	If you want a larger sample size to be used in computing the parts counting conversion factor, add pieces (the balance will count them) until the decimal part is near 0.7 or 0.3. Then press the ZERO button.	The balance will round to the nearest whole number but still show the decimal places. This step may be repeated as many times as you desire.	
6	When you are satisfied the sample size is large enough, press the ZERO button once again.	The balance rounds to the nearest whole number, the decimal places disappear, and PCS lights steadily.	
7	When you wish to count something else, press the MODE button.	You are now back at Step 2 with a flashing PCS and 0.	
8	If you want to exit the counting mode, press the MODE button again.	You are now in the weighing mode you used just before selecting the parts counting mode.	

#### (HI-OK-LO) Checkweighing / Process Control Limits:

ĺ	User Action	Balance Response
1	Press the FUNCTION button (or MODE and	Display cycles repeatedly through PCS, HI-OK-LO, CAL1, CAL2, $\overline{T}$ , and %.
	RANGE buttons simultaneously for dual	
	range models).	
2	Press the MODE button when HI OK LO	HI, LO and 0 flash.
	appears on the display.	
3	Press the ZERO button.	HI flashes and zeros are displayed.
4	Place weight on the weighing pan which	HI flashes and the upper weight limit is displayed.
	represents the upper control limit of the	
	acceptable weight range.	
5	Press the ZERO button.	LO flashes and the upper weight limit is displayed.
6	Remove the upper limit weight and place	LO flashes and the lower weight limit is displayed.
	weight on the weighing pan which represents	
	the lower control limit of the acceptable	
	weight range.	
7	Press the ZERO button.	HI OK LO briefly appears and then OK and the lower weight limit are
		displayed.
8	Remove the lower limit weight.	LO appears and zeros are displayed.

The balance is now ready to checkweigh samples. The balance displays OK along with the weight of the sample if the sample is within the acceptable weight range. If the sample is too heavy, HI and the weight are displayed. If the sample is too light, LO and the weight are displayed. The weight limits are stored until the balance is turned off.

To exit check weighing, press the MODE button. The balance then returns to normal operation.

## (%) Percent Weighing:

	User Action	Balance Response
1	Place an empty container on the weighing pan	Zeros are displayed.
	and press the ZERO button.	
2	Place the sample which represents 100% in the	Display indicates the weight of the sample in the unit of measure you have
	weighing container.	selected.
3	Press the FUNCTION button (or MODE and	Display cycles repeatedly through PCS, HI-OK-LO, CAL1, CAL2, $\overline{T}$ , and %.
	RANGE buttons simultaneously for dual	
	range models).	
4	Press the MODE button when CAL 100	Display will indicate % and 100.00. This means that the weight on the pan now
	appears on the display.	represents 100.00%. You are now in the percent weighing mode with all
		weight readings displayed as a percentage of the weight of the sample used in
		Step 2.
5	If you want to exit the percent weighing mode,	You are now in the weighing mode you used just before selecting percent
	press the MODE button.	weighing.

## $(\overline{T})$ Live Animal Weighing / Severe Environment Weighing:

	User Action	Balance Response	
1	Press the FUNCTION button (or MODE and RANGE buttons simultaneously for dual range models).	Display cycles repeatedly through PCS, HI-OK-LO, CAL1, CAL2, $\overline{T}$ , and %.	
2	Press the MODE button when $\overline{T}$ appears on the display.	$\overline{T}$ appears in the display and you are now in the time averaging weighing mode.	
3	Place a container/cage on the pan.	$\overline{T}$ appears in the display as well as a slowly increasing weight of the container/cage.	
4	When the display has stabilized, press the ZERO switch to zero out the container/cage weight.	$\overline{T}$ appears in the display as well as zeros.	
5	Remove the container/cage and place the sample/animal in the container/cage.	A slowly decreasing negative weight is displayed.	
6	Replace the container/cage with the enclosed sample/animal on the weighing pan	After the sample/caged animal is placed on the pan, the weight reading will slowly stop decreasing and then slowly start increasing as the weight reading is averaged over time. When the weight stops drifting upward, you have reached the final time averaged weight reading.	
7	If you want to reach the final time averaged weight reading more quickly, press the FUNCTION switch (or the RANGE switch on dual range models). This resets the time averaging mode.	The final time averaged weight reading is reached more quickly.	
8	If you want to exit the time averaging weighing mode, press the MODE switch.	You are now in the weighing mode you used just before selecting the time averaging mode.	

## Floating Tare<sup>TM</sup> (dual range models only):

Floating tare is only active when the balance is in LO range. Floating tare yields low range resolution throughout the entire high range capacity of the balance. A typical example using floating tare would be where you combine different components by weight to produce compounds. The procedure is as follows.

- 1. Select LO range by pressing the RANGE button until LO briefly appears in the display.
- 2. Place container on weighing pan. If the container weight exceeds LO range capacity, OL is displayed. If the container weight does not exceed the LO range capacity, the container weight is displayed.
- 3. Press the ZERO button. The display returns to zeros and LO range.
- 4. Add the first component until the target weight is reached. Then press ZERO.
- 5. Add the second component until the target weight is reached. Then press ZERO.
- 6. Continue until all components have been added.

Floating tare allows you to enter the LO range from anywhere within the full capacity range of the balance. This feature is particularly useful when adding small amounts to large tare loads and compounding where weights are accumulated. Floating tare is only active when the balance is in LO range. Pressing the ZERO button returns the display to zeros in LO range. While you are using the floating tare feature, it is easy to lose track on how much capacity has been used. For this reason the Capacity Tracking feature is a helpful tool. Please see the discussion under that heading.

## **Capacity Tracker:**

The capacity tracker provides a graphic display of the used and unused portions of the weighing range and is shown in Figures 4 and 5. Each segment represents 10% of the balance's total capacity. As 10% of the balance's capacity is used the first segment will illuminate. As 20% of the balance's capacity is reached the second segment will light and so on.

### Selectable Filters, Stability Indicator, and Send-When-Stable:

All balances are equipped with three user-selectable vibration filters which reduce nervous readings in varying weighing conditions. The balance was delivered to you set in the high filtering mode (Fil HI). This is the most aggressive filtering mode. Normal filtering (Fil nor) and low filtering (Fil Lo) can be selected for quieter conditions and faster response.

The stability indicator, OK, is illuminated when the balance has determined that all readings are within the stability parameters as selected by the user. The balance was delivered to you with stability set at  $\pm 2$  display counts, which is represented by a 2 in step 5 below. You may select stability from  $\pm 1$  to  $\pm 10$  display counts manually in step 5 below. If the weight readings are outside the acceptable limits, the stability indicator will not light. The stability indicator can be disabled, if desired. Also, the send-when-stable command sends the weight reading over the RS-232 interface whenever the OK light illuminates. The balance was delivered to you with the send-when-stable command OFF. When it is ON, the auto and continuous send commands (see RS-232 Front Panel Configuration for details) are not functional.

To enter the selection mode proceed as follows: To exit the selection mode and return to normal operation, turn the balance off and then back on again at any time.

	User Action	Balance Response	
1	Turn the balance off using the ON/OFF	Display blanks.	
	Button.		
2	Hold the MODE button down while turning	The current filter, Fil nor (filtering normal), Fil Lo (filtering low), or Fil HI	
	the balance on using the ON/OFF switch.	(filtering high) and OK are displayed.	
3	Press the SEND button until the desired	SAVEd OK is displayed followed by the current stability indicator setting, Si	
	vibration filter is displayed. Then press the	on (stability indicator will turn on when reading is stable) or Si oFF (stability	
	ZERO button to save the setting.	indicator will always be turned off).	
4	Press the SEND button until the desired	SAVEd OK is displayed followed by the current stability sensitivity setting	
	stability indicator Si setting is displayed.	SEnS (the default is $\pm 2$ display counts).	
	Then press the ZERO button to save the		
	setting.		
5	Press the SEND button until the desired	SAVEd OK is displayed followed by the current send-when-stable SS setting	
	stability sensitivity display counts setting is	(oFF is the default).	
	displayed. Then press the ZERO button to		
	save the setting.		
6	Press the SEND button until the desired send	SAVEd OK is displayed. Then the balance cycles back to Step 2 and shows	
	when stable SS command is displayed. Then	the current filter setting.	
	press the ZERO button to save the setting.		
7	Press the ON/OFF button.	The display blanks.	
8	Press the ON/OFF button.	The balance returns to normal operation with the new vibration filter and	
		stability indicator settings in place.	

To return the balance to the default settings repeat steps 1 through 3, then turn the balance off and back on again.

### **Density Determination:**

Scientech does not offer a density determination kit nor do you need one to determine density. Density is mass (grams) per unit volume (cubic centimeters).

In order to determine density of a solid, place a graduated flask with a known volume of water on the pan of the balance, tare the balance, and then place the solid in the flask of water. Divide the displayed weight in grams by the increased volume of water. The result is the mass per unit volume of the solid in g/cc.

To determine the density of a liquid, place an empty graduated flask on the balance weighing pan, tare the balance, then pour the liquid into the graduated flask. Divide the displayed weight in grams by the volume of the liquid. The result is the mass per unit volume of the liquid in g/cc.

### **Below Balance Weighing:**

Note: Please use care when installing Below Balance Weighing. The suspension can be damaged if over tightened. The overload protection which is built into the pan assembly is not available at the below balance hanging device. Therefore, care must be taken to avoid side shocks or pulling too hard on the hanging device.

For applications requiring suspension of weighings below the balance, a 6-32 threaded screw is provided. To access the set screw, proceed as shown. Then mount the balance on a solid pedestal or surface with a hole under the balance to allow access to the hanger. While using the below balance weighing feature all other functions of the balance operate normally. The balance is capable of weighing both above and below simultaneously provided the capacity of the unit is not exceeded.




Figure 6 Below Balance Weighing

### **Specific Gravity Determination:**

The below balance weighing apparatus shown previously is ideal for determining specific gravity. Specific gravity is the ratio of the mass of a body to the mass of an equal volume of water. Every mineral has its own specific gravity (SG). A list may be found in any Handbook of Chemistry and Physics. Specific gravity will classify or authenticate a substance. For instance, a diamond's SG is 3.50-3.53 while quartz's is 2.65.

To determine specific gravity using our balance:

- 1. Install a below balance weighing hangar as shown in the previous section.
- 2. Install a below balance weighing apparatus, such as a wire hook, including a pan suspended in a bowl of water. Insure that the pan and the hanger do not touch any part of the bowl and all are totally submerged. Then tare the balance.
- 3. Then place the sample to be tested on the balance pan and record the weight reading shown on the display. You may use any unit of measure you desire.
- 4. Then place the same sample to be tested on the pan suspended in the bowl of water. Make sure that the sample is completely submerged in the water and record the weight reading shown on the display.
- 5. Subtract the reading in Step 4 from the reading in Step 3.

EXAMPLE:

6. Divide the reading in Step 3 by the number calculated in Step 5. The result is the SG of your sample.

Reading in Step 3 = 6.50Reading in Step 4 = 4.25Subtraction = 2.25Division (Step 6) = 6.50/2.25 = 2.89 specific gravity

#### **Security Bracket:**

A security bracket is provided on the rear panel providing a convenient method of securing the balance.

# **Options:**

Remote Weighing (7000-04) and Custom Unit of Measure (9000-90) options must be installed at the factory or by personnel authorized by Scientech. Other options, such as a Scientech printer, may be purchased at any time. Please contact Scientech at (303)444-1361 or (800) 525-0522 or email us at inst@scientech-inc.com for information.

### **Optional RS-232 Printers:**


#### Note: Printers must be serial.

There are a few different models to choose from. Please contact Scientech or one of our representatives for more information. A comprehensive manual is included with each printer when purchased. All printers are set for a 9600 baud rate. To change this setting please see the printer manual and the RS-232 Front Panel Configuration section. The balance display contents can be sent to the printer at any time by pressing the balance front panel SEND switch. Balances only communicate with serial printers.

# **RS-232 Interface:**

Note: Scientech balances are DTE (computer) devices. If communicating to another DTE device (ie computer), a Scientech RS-232 cable, PN10697, or normal null modem cable is required. If you are communicating to a DCE device (printer), a serial cable is required. Scientech offers a serial cable, PN11367, for your convenience.

Your balance is equipped with a bi-directional RS-232 compatible interface. The interface is uni-directional (balance send only) when the local control is set to ON. To enable the bi-directional interface, set the local control to OFF (see the RS-232 Front Panel Configuration section). The RS-232 connector is a 9 pin D subminiature connector located on the balance rear panel. The pin out and pin descriptions are shown in Figure 7.



The balance will not output any information under any circumstances unless pin 8 (CTS) is held in an ON state (+3 to +15 VDC). Interfaces not utilizing the CTS handshake may tie pin 8 to pin 7 or pin 8 to pin 4 to defeat it.

This interface does not strictly adhere to the official RS-232 standard. However, it emulates what has become commonplace in the microcomputer industry.

#### **RS-232 Specifications:**

Туре	EIA-RS-232C, DTE		
Method	Half-duplex, Asynchronous Transmission, Bi-directional		
Format	300, 600, 1200, 2400, 480	00, 9600 and 19,200 baud rate selectable (default is 9600)	
	Code: ASCII		
	For parity Even or Odd:	Data bit 7, Stop bit 1.	
	For parity none:	Data bit 7, Stop bit 2.	

Note: Parity none, Data bit 8, Stop bit 1 does function, but is not technically correct.

### **RS-232 Front Panel Configuration:**

Before using the RS-232 feature of your balance, it is necessary to configure the interface properly for your application. The RS-232 Configuration Mode allows you to set baud rate, front panel control, software protocol, parity, auto send, continuous send, and display blanking. The balance is configured with defaults at the factory. The default modes are shown in parenthesis below.

It is not necessary to follow the entire configuration procedure if only one parameter is to be changed. Follow Steps 1 and 2, then use the MODE switch to select the parameter to be changed, skipping the others. Select the desired setting using the SEND switch, save the setting using the ZERO switch, then turn the balance off and then on again with the ON/OFF switch.

To enter the RS-232 configuration mode via the front panel, proceed as follows:

	User Action	Balance Response
1	Turn the balance off using the ON/OFF button.	Display blanks.
2	Hold the SEND button down while turning the balance on using the	The current baud rate, br300, br600, br1200, br2400,
	ON/OFF button.	br4800, br9600, or br19,200 and OK are displayed.
3	BAUD RATE SELECTION (9600 is default).	
	Press the SEND button until the desired baud rate is displayed. Then	SAVEd OK is displayed followed by the chosen baud
	press the ZERO button.	rate and OK.
4	LOCAL CONTROL SELECTION (LC on is default). "LC on" means	
	that the front panel switches control the balance. To enable a computer to	
	control the balance, "LC oFF" must be selected.	
	Press the MODE button.	The current front panel control setting, LC on or LC oFF
		and OK are displayed.
	Press the SEND button to choose between on or off. Then press the	SAVEd OK is displayed followed by the chosen setting
	ZERO button.	and OK.

	User Action	Balance Response
5	PROTOCOL or HANDSHAKE SELECTION (Pr on is default).	
	Press the MODE button.	The current software protocol setting, Pr oFF or Pr on and OK are displayed.
	Press the SEND button to choose between on or off. Then press the ZERO button.	SAVEd OK is displayed followed by the chosen setting and OK.
6	PARITY SELECTION (PA nonE is default).	
	Press the MODE button.	The current parity setting, PA EVEn, PA odd, or PA nonE and OK are displayed.
	Press the SEND button to choose between EVEn, odd, or nonE. Then press the ZERO button.	SAVEd OK is displayed followed by the chosen setting and OK.
7	AUTO SEND SELECTION (AS oFF is default). "AS on" means the balance will automatically send the display contents over the RS-232 interface at the selected time interval placed into register 89. This time interval may be inputted via the optional PDA or through Type 4 RS-232 commands. Refer to these sections for instructions. A time and date stamp may also be sent at the same time (see Type 4 RS-232 Commands section). The auto send selection is not functional if the send-when-stable command is on (see Selectable Filter section).	
	Press the MODE button.	The current auto send setting, AS oFF or AS on ond OK are displayed.
	Press the SEND button to choose between on or off. Then press the ZERO button.	SAVEd OK is displayed followed by the chosen setting and OK.
8	CONTINUOUS SEND SELECTION (CS oFF is default). "CS on" means the balance will automatically send the weight reading over the RS-232 interface at the baud rate selected. Display readings are updated every 200 milliseconds. The continuous send selection is not functional if the send- when-stable command is on (see Selectable Filter section).	
	Press the MODE button.	The current continuous send setting, CS oFF or CS on and OK are displayed.
	Press the SEND button to choose between on or off. Then press the ZERO button.	SAVEd OK is displayed followed by the chosen setting and OK.
9	DISPLAY BLANKING SELECTION (bL on is default). "bL on" means that every time data is sent over the RS-232 interface, the display will blink.	
	Press the MODE button.	The current display blanking setting, bL on or bL oFF and OK are displayed.
	Press the SEND button to choose between on or off. Then press the ZERO button.	SAVEd OK is displayed followed by the chosen setting and OK.
10	Press the ON/OFF button.	The display blanks.
11	Press the ON/OFF button.	The balance returns to normal operation with the new RS-232 configuration.

### **Using Bi-Directional Communications:**

Scientech electronic balances, interfaced to a computer via the RS-232 port, can be controlled by a computer program in the same way an operator would control the balance using a PDA. Any programming language with access to the RS-232 interface can be used to program this control. The balance expects ASCII character instruction strings and responds with ASCII character data strings. All characters with an ASCII value less than the space character (decimal 32 of hex 20), are ignored by the balances.

If local control has been enabled (LC on) via RS-232 front panel configuration, RS-232 communication is limited to balance sending only as all incoming RS-232 command strings are ignored by the balance. To enable bi-directional RS-232 communication, set the local control to off (see RS-232 Front Panel Configuration section).

# **Bi-Directional RS-232 Command Set:**

The following commands can be sent to the balance in any combination of upper and lower case characters. No action is taken by the balance until it receives a carriage return indicating the end of the command string. Each command's syntax is described using this notation; keywords are in upper case; items in [] are required; when one item must be chosen from a list, each choice is enclosed in (); CR means the carriage return or enter character; LF means the line feed character; and \_ indicates a single space character. A command string or entry is considered to be a keyword (and/or a numeric string) followed by a carriage return. The commands are listed by type.

- Type 1 commands are balance control functions.
- Type 2 commands are balance input functions.
- Type 3 commands are balance output functions.
- Type 4 commands are clock/calendar functions.

Where a balance response is given, no attempt has been made to show the actual message formats. You should refer to the section on balance message formats for detailed information. Numbers stored in the registers are classified by the balance software as being additive, multiplicative, or unflagged. Additive numbers are used by the balance software in addition and subtraction operations. Multiplicative numbers are used in multiplication and division operations. Unflagged numbers aren't used in any arithmetic functions. If you try to use an additive number in a function which requires a multiplicative number the balance responds with the register contents (if applicable) and a ? and the instruction is ignored.

### **Type 1 Commands – Balance Control Functions:**

Command	Response	Purpose
CLEAR [CR]	None	Clears the previous command and resets the balance to normal operating mode. The Tare register is cleared to zero and the balance is zeroed.
HI_RANGE[CR] or LO_RANGE[CR] or AUTO[CR]	None	Set the balance range.
GRAMS[CR] or KG[CR] or MG[CR] or CARATS[CR] or DWT[CR] or OZT[CR] or OZ[CR] or LB[CR] or A[CR] or LIMITS[CR] or CAL1[CR] or CAL2[CR]	None	Places the balance in the indicated mode or units. To abort any of the CAL sequences or the LIMITS modes use CLEAR[CR].
ZERO[CR]	None	The balance takes whatever action it would in response to a push of the front panel zero switch. Normally tares the balance.
TARE[CR]	None	If the balance is in the weighing mode, this command tares the balance, otherwise it is ignored.
[decimal number]_HI[CR]	None	Sets the check weighing high limit register (register 88) to the decimal number entered in the current units. Register 88 is undefined at every ON/OFF cycle.
[decimal number]_LO[CR]	None	Sets the check weighing low limit register (register 87) to the decimal number entered in the current units. Register 87 is undefined at every ON/OFF cycle.
[decimal number]_CONVERT[CR]	None	Loads the number entered, as a "last front panel units" relative multiplier, into the CONVERT register and enters the CONVERT mode. CLEAR exits the convert mode and un-defines the convert register.
[decimal number]_CAL[CR]	None	Loads a computed number based on the entered number, as a "last front panel units" relative multiplier, into the CAL register and enters the CAL mode. The display must be non-zero when this command is issued. If the display is zero, a 3 second "Err" message is displayed and the balance returns to its normal weighing mode. The current weight reads as the number entered with the appropriate sign. CLEAR exits the CAL mode and un-defines the CAL register.
[integer]_PIECES[CR]	None	Loads a computed number based on the entered number, as a "last front panel units" relative multiplier, into the PIECES register and enters the PIECES mode. The display must be non-zero when this command is issued. If the display is zero, a 3 second "Err" message is displayed and the balance returns to its normal weighing mode. CLEAR exits the pieces mode and un-defines the pieces register.

Command	Response	Purpose
[decimal number]_PCT[CR]	None	Puts the balance on the percent weighing mode with the displayed reading converted to the percent entered. The display must be non-zero when this command is issued. If the display is zero, a 3 second "Err" message is displayed and the balance returns to its normal weighing mode. CLEAR exits the percent mode and un-defines the percent register.
[Decimal number]_ENTER_[integer] _PIECES[CR]	None	Accepts the decimal number as a weight in "last front panel units" per integer pieces. If the balance is not in PCS mode, it goes into PCS mode using the decimal number/the integer as the weight. If used when the balance is already in PCS mode, the display digits are blanked for about 1 second while the PCS and "last front panel units" annunciators are lit. The balance then resumes normal PCS operation using the decimal number/the integer as the unit weight.
[register	REG XXX : [register	Puts the recalled register contents into the specified mode
number]_RCL_[(CONVERT) (CAL) (PIECES)][CR]	contents][MULT.]	register and enters that mode.
TAVG[CR]	None	Clears the TBAR registers and enters the TBAR mode.
RESET_TAVG[CR]	None	Clears the TBAR registers. If the balance is in the TBAR mode, the process keeps running.
XAVG[CR]	None	Accumulates the current weight in the XBAR registers.
RESET_XAVG[CR]	None	Clears the XBAR registers.
GLP[CR]	Sends GLP header	Puts balance in the GLP mode.
XAVG[CR]	Sends weight while in GLP	Accumulates the current weight in the XBAR registers.
RCL_XAVG[CR]	Sends statistics and signature line	Terminates GLP mode.
ISO[CR]	Sends ISO header and waits for target weight entry	Puts balance in ISO mode.
xxx.xx_Targ[CR]	Sends target weight (g)	Enter target weight value in grams.
SEND[CR]	Sends weight, difference between weight and target, and signature line	Terminates ISO mode.
ASON[CR] or ASOFF[CR]	See the RS-232 Balance Message Formats section.	Turns auto send on or off. When auto send is on, a time interval must be entered into register 89 (see Type 4 commands).
CSON[CR] or CSOFF[CR]	See the RS-232 Balance Message Formats section.	Turns continuous send on or off.
ACAL[CR]	None	Starts the automatic internal calibration weight calibration routine.
SSON[CR] or SSOFF[CR]	See the Selectable Filter section.	Turns send when stable on or off.

# **Type 2 Commands – Balance Input Functions:**

Command	Response	Purpose
[register number]_STORE[CR]	None	Stores the current weight, at the greatest possible resolution, in the specified register.
[Decimal number]_ENTER_[register number]_STORE[CR]	None	Stores the number entered, in the current units, as an additive constant in the register specified.
[decimal number]_ENTER_CONVERT_[register number]_STORE[CR]	None	Stores the number entered, as a "last front panel units" relative multiplier, in the specified register.
[decimal number]_TARE[CR]	None	Adds the number entered, in current units, to the TARE register. CLEAR [CR] zeroes the TARE register.
[decimal number]_ENTER_86_STORE[CR]	None	Stores the desired precision of the displayed weight for $\overline{T}$ mode.

Command	Response	Purpose
SEND[CR]	See the RS-232 Balance Message Formats section.	Returns the contents of the display register.
[register number]_RCL[CR]	REG XXX:[register contents][current units or 'MULT.'] [CR] [LF]	Sends the contents of the specified register in the current units if it is additive or with the designator 'MULT.' if it is multiplicative. An unflagged number is sent with no designator. An undefined register returns a ? with a [CR][LF].
RCL_TARE[CR]	REG 091:[TARE register contents] [current units][CR][LR]	Return the TARE register's contents.
RCL_[(CONVERT)(CAL)]	REG XXX:[contents of specified register][MULT.][CR][LF]	Returns indicated register contents, if in that mode. If not in that mode then a ? with a [CR][LF] is returned.
RCL_PIECES[CR]	REG XXX:[contents of pieces register][last FP units/pc][CR][LF]	Returns pieces register contents expressed as last front panel units/pc, if in that mode. If not in that mode then a ? with a [CR][LF] is returned.
[register number]_RCL_TARE[CR]	REG XXX:[register contents][current units][CR][LF]	Adds the specified register contents to the TARE register.
RCL_XAVG[CR]	[average weight] [current units] AVX[CR][LF]. [2 second delay]. [number of samples taken] ###[CR][LF]. [2 second delay]. [standard deviation] [ current units] SDEV[CR][LF]. [2 second delay]. [relative standard deviation] COV[CR][LF].	Sends the results of a standard deviation run. The TBAR mode, if in use, is temporarily suspended while this process is going on.

# **Type 3 Commands – Balance Output Functions:**

# **Type 4 Commands – Clock/Calendar Functions:**

Command	Response	Purpose
[six digit integer]		Sets the calendar function, if available, to the specified
_ENTER_100_STORE[CR]		date. The date must be specified in the MMDDYY
		format and no delimiters.
100_RCL[CR]	REG 100: MM.DD.YY DATE[CR][LF]	Returns the date.
[six digit integer]		Sets the clock function, if available, to the specified
_ENTER_101_STORE[CR]		time. The time must be specified in the HHMMSS
		format using military 24 hour time format.
101_RCL[CR]	REG 101: [HH:MM:SS]	Returns the current time, using military 24 hour time
	TIME[CR][LF]	format, once for each request.
[1 to 6 digit integer]		Sets the auto send register to the specified send time
_ENTER_89_STORE[CR]		interval. For the auto send feature to be operational,
		you must set the auto send selection to ON (see RS-
		232 Front Panel Configuration section for details).
		The format used is HHMMSS with no delimiters. For
		instance, to set the auto send interval to 5 minutes and
		25 seconds, you would send this command string: 525
		ENTER 89 STORE[CR]. Also you must have the auto
		Send selection set to ON before the auto Send will
		work (see RS-232 Front Panel Configuration Section).
89_RCL[CR]	REG 089: [HH:MM:SS]	Returns the auto SEND time interval currently set.
	INTV[CR][LF]	
[(1)(0)]_ENTER_79_STORE[CR]		A 1 in register 79 disables the date/time stamp feature
		of any SEND. A 0 in register 79 enables the date/time
		stamp.

### **RS-232 Balance Message Formats:**

The balance will respond to a SEND command by transmitting a message in one of three formats depending on how the SEND command was issued. The following discussion defines four types of SEND commands and the three message formats.

- 1. The first case typically applies to a balance with RS-232 connected to a printer and an external print switch. If the SEND is initiated by activation of the hardware SEND line on the RS-232 I/O module and the display shows the current weight, then the response will be a format B. If the display does not show the current weight (i.e., date, time, or a register RCL), the hardware SEND is ignored.
- 2. This case typically applies to a balance with the RS-232 interface connected to a printer. If the SEND is initiated by a time or auto SEND and the display shows the current weight, then the response will be a format B. The date/time stamp is included in format C if register 79 has been set to 1 prior to setting register 89 to the desired time interval. To stop auto sending set register 89 to 0. If the date/time stamp is enabled and the display doesn't show the current weight, the date/time stamp is still sent. Nothing is sent if the date/time stamp is disabled and the display doesn't show the current weight.
- 3. This case typically applies to a balance with the RS-232 interface connected to a computer. There are several RS-232 I/O commands containing the keyword RCL. These commands, issued by the computer, all cause a single format C or a sequence of format C send to occur.
- 4. This case also typically applies to a balance with the RS-232 interface connected to a computer. A SEND command issued over the RS-232 I/O channel, by the computer, causes an unconditional format A send.

#### Format A - Balance in the normal weighing mode:

1	2	3	4	5	6	7	8	9	10	11	CR	
Х	Х	Х	Х	Х	Х	Х	-	-	-	Y		LF

X = a digit (0-9) or a decimal point or a space or a minus sign.

Y = an upper case alphabetic character (A-Z). The first character of the units or mode annunciator in the display, followed by the rest of the characters of the annunciator.

If the display shows a minus sign, it is the first character in the balance message. In this case the least significant digit of the displayed number is in position 8 followed by only two spaces instead of three. The 1st character of the units annunciator is still in the 11th position.

Here are some examples. The notation used here is that CR means the carriage return or enter character; LF means the line feed character; and \_ indicates a single space character. Note that all space characters are shown explicitly.

Display shows 5.15 g Message is \_\_\_\_5.15\_\_\_G CR LF Display shows 211.05 dwt Message is \_\_\_211.05\_\_\_DWT CR LF Display shows -211.05 dwt Message is \_\_\_211.05\_\_DWT CR LR

Display shows .0035 A Message is \_\_.0035\_\_\_A\_SPEC. CR LF

#### Format A - Balance in a special weighing mode:

Display shows 1250 PCS Message is \_\_1250\_\_\_\_PCS CR LF

Note that, in these special weighing modes, the least significant digit of the numeric field is in the 6th (or 7th position if the number is negative) and that the leftmost character of the annunciator is in the 12th position.

Display shows -100.00 CAL Message is -100.00\_\_\_CAL CR LF

Display shows sigma Tbar 0.00 g Message is \_\_\_\_0.00\_\_\_G\_SIGMA\_\_TBAR\_ CR LF

#### Format B - Balance in normal weighing mode:

				-	-								
1	2	3	4	5	6	7	8	9	10	11	12	13	14
15													
Х	Х	Х	Х	Х	Х	Х	_	_	_	Y	Y	Y	_
_	Y	Y	CR	LF									

Display shows 5.15 g and balance in high range Message is \_\_\_\_5.15\_\_\_G\_\_HIGH CR LF

#### Format B - Balance in a special weighing mode:

Display shows 1250 PCS and balance in low range Message is \_\_1250\_\_\_\_PCS\_LOW CR LF

Note that, in these special weighing modes, the least significant digit of the numeric field is in the 6th (or 7th position if the number is negative) and that the leftmost character of the annunciator is in the 12th position.

#### Format C:

1	2	3	4	5	6	7	8	9	10	11	12	13	14	15
	16	17	18	19	20	21	22	23						
R	E	G	:	_	Х	Х	Х	_	_	Х	Х	Х	Х	Х
									CR LI					

Display shows the contents of register 24 as 102.56, an additive constant, with units in grams Message is REG:\_024\_\_102.56\_\_G CR LF

Display shows 12:03:35 as the time Message is REG:\_101\_12:03:35\_\_\_TIME CR LF

#### **Bi-Directional RS-232 Error Messages:**

There are three single character error messages that the balance issues when certain errors occur during bi-directional communications. Each error character is followed by CR LF.

- 1. ! is issued when the input buffer is full. Normally this occurs because a CR is lost or the command string is too long. The balance has a 37 character input buffer which is sufficiently long for all valid command strings. The ! is issued as soon as the buffer is full and is repeated after each successive character until a CR is received. In response to the CR, a ? and CR/LF is sent and the balance input buffer is cleared.
- 2. : is issued when a parity, overrun, or framing error is detected by the interface since the last CR. The : is sent after the CR ending the command string which caused the error has been received.
- 3. ? is issued when a syntax error occurs or when an illegal character is received or when some other procedural error is detected. The ? is sent after the CR ending the command string which caused the error has been received.

Power up errors are not detectable over the RS-232 I/O channel. The only way to detect such errors is to attempt to communicate with the balance and have the ability to recognize that the communication is failing. Displayed error messages are only available by polling the balance using the SEND command. The balance would respond by transmitting the displayed error (i.e., Err 1, Err 2).

# **Troubleshooting Guide:**

Note: Many problems such as the balance remaining in the turn on sequence, "weird" characters on the display or "garbage" on the display are caused by connecting the power supply to the balance incorrectly. The proper procedure is to connect the round DIN connector on the power supply cable to the balance then plug the power supply into the wall outlet.

Problem	Possible Cause	Possible Solution
The display is blank	*Balance not turned on	*Press ON/OFF switch
	*Power cable not plugged in	*Plug in cable, press ON/OFF switch
	*No power from AC outlet	*Turn on circuit breaker
		*Change AC outlets
OL appears in display	*Maximum capacity exceeded	*Reduce container weight
		*Weigh sample in smaller increments
		*Switch to high range (dual range units)
	*Shipping clamp is engaged	*Disengage clamp – see page 4
UL appears in display	*Pan is not in place	*Insure pan is positioned properly
	*Balance is out of range	*Press ZERO switch
	*Shipping clamp is engaged	*Disengage clamp – see page 4
The display is unstable	*Drafts (air currents are present)	*Install windscreen, relocate balance
	*Vibrations are present	*Isolate balance from vibration, relocate balance
Weight readings are incorrect	*Balance is out of calibration	*Recalibrate balance
	*Balance is not level	*Level balance
	*Display was not zeroed before weight was	*Press ZERO switch before weighing
	placed on pan	
	*Object being weighed is touching windscreen	*Reposition object
	or balance case top	
	*Unit of weight selection is incorrect	*Select proper weighing mode
Display stays in turn on sequence	*Pan not in place	*Place pan on balance
	*Drafts or vibrations present	*Isolate or relocate balance
	*New windscreen has been installed	*Raise pan height
	*Shipping clamp is engaged	*Disengage clamp – see page 4
	*Power supply connected to wall outlet before	*Unplug power supply from wall then replug
	balance connector	into wall
Err 1 appears in display	*Calibration weight is incorrect	*Use calibration weight that appears in balance
		display
Err 2 appears in display	*Balance not warmed up enough for calibration	*Plug in and turn on balance for 1 hour
	to be performed	
Err 3 through 14 appears in	*Service is required	*Call Scientech's Service Department at (800)
display		525-0522 or (303)444-1361 or email us at
		inst@scientech-inc.com.
Err appears in the display	*Procedural error	*Review procedure in manual and try again

# **Environmental Requirements:**

This product is intended for indoor use at altitudes up to 2000 meters, Pollution Degree 1 or 2 in accordance with IEC 664 and transient overvoltages according to Installation Categories (Overvoltage Categories) I, II and III. For mains supply, the minimum and normal category is II.

# **CE Mark:**

All Scientech Electronic Balances carry the CE Mark and conform to the requirements of the following standards:EN 55011: 1998Limits and Methods of Measurement of Radio Disturbance Characteristics of Industrial, Scientific and Medical (ISM) Radio-frequency EquipmentEN 61326-1: 1997EMC Requirements for Electrical Equipment for Measurement, Control and Laboratory UseEN 61010-1: 1993Safety Requirements for Electrical Equipment for Measurement, Control and Laboratory Use

# **Specifications for SM Semi Micro Balances:**

Note: Balances with an Internal Calibration Weight have an "IW" suffix in their model number. Their specifications are the same as the models in the table below.

Model	SM 50	SM 99	SM 124D	SM 128D		
Weighing Mode	Single I	Range	Dual R	al Range		
			(Floating	Tare™)		
Capacity	50g	99g	40g	80g		
			120g	120g		
Readability	.000	D1g	.0000			
			.000			
Tare Range	0-50g	0-99g	0-120g	0-120g		
			0-120g	0-120g		
Repeatability	.00002g	.00004g	.00002g	.00003g		
(Standard Deviation)			.0001g	.0001g		
Linearity	±.00003g	±.00003g	±.00003g	±.00003g		
			±.0002g	±.0002g		
Stabilization Time		~8 \$	Seconds			
Weighing Speed		Ac	laptive			
Display Update Interval		8	00ms			
Data Interface	RS-232 bidirectional	nterface is standard. Baud ra	tes are 300, 600, 1200, 2400, 4800	0, 9600 and 19,200.		
Pan Size		Circular 3.5	5 inch diameter			
Operating Temperature		5°C	to 40°C			
Relative Humidity	80 9	% for temperatures up to 31°C	C decreasing linearly to 50 % at 40	°C		
Power Supply		Automatic switching 115	5/230 Volts, 50/60 Hz ± 10%			
Windscreen		7.5W x 8	3.25D x 9.5H			
Calibration Weight	50g	100g	100g	100g		
	10g	50g	40g	50g		
Housing (WxDxH)	-		1.25" x 3.25"			
Weight		~ 1	3.8 lbs			

# **Specifications for SA Analytical Balances:**

Note: Balances with an Internal Calibration Weight have an "IW" suffix in their model number. Their specifications are the same as the models in the table below.

Model	SA 80	SA 120	SA 210	SA 310	SA 410	SA 510	SA 210D	SA 525D			
Weighing Mode	Single Range							Dual Range			
							(Floating	(Floating Tare™)			
Capacity	80g	120g	210g	310g	410g	510g	100g	250g			
							200g	500g			
Readability			.00	01g				01g			
		1	1					01g			
Tare Range	0-80g	0-120g	0-210g	0-310g	0-410g	0-510g	0-200g	0-500g			
							0-200g	0-500g			
Repeatability	.0001g	.0001g	.0001g	.00015g	.00015g	.0002g	.0001g	.00015g			
(Standard Deviation)							.0005g	.0005g			
Linearity			±.00	)02g				)02g			
							±.00	)05g			
Stabilization Time				User Se	electable						
Weighing Speed				Adaj	ptive						
Display Update Interval				200	)ms						
Data Interface	RS-2	232 bidirectiona	l interface is star	ndard. Baud rate	s are 300, 600,	1200, 2400, 480	00, 9600 and 19	,200.			
Pan Size				Circular 3.5 i	nch diameter						
Operating Temperature				5°C to	o 40°C						
Relative Humidity		80	% for temperatu	ires up to 31°C o	decreasing linea	rly to 50 % at 40	С°С				
Power Supply			Automatic	switching 115/2	230 Volts, 50/60	Hz ± 10%					
Windscreen				7.5W x 8.2	25D x 9.5H						
Calibration Weight	80g	100g	200g	300g	400g	500g	200g	500g			
-	50g	50g	100g	200g	200g	200g	100g	200g			
Housing (WxDxH)			-	7.5" x 11.2	25" x 3.25"						
Weight				~ 13.	.8 lbs						

# **Specifications for SP Precision Balances:**

Model	SP150	SP250	SP350	SP500	SP1000	SP1500	SP404D	SP510D	SP2050D		
Weighing Mode		·	Dual Range								
	Single Range							(Floating Tare <sup>™</sup> )			
Capacity	150g	250g	350g	500g	1000g	1500g	40g	100g	500g		
				01g			400g	500g	2000g		
Readability			0.001g								
			0.01g								
Tare Range	0-150g	0-250g	0-350g	0-500g	0-1000g	0-1500g	0-400g	0-500g	0-2000g		
							0-400g	0-500g	0-2000g		
Repeatability	0.001g							0.001g			
(Standard Deviation)	0.005g										
Linearity	±0.0015g							±0.0015g			
Otabilization Time	±0.005g										
Stabilization Time	User Selectable										
Weighing Speed					Adaptive						
Display Update Interval	200 ms RS-232 bidirectional interface is standard. Baud rates are 300, 600, 1200, 2400, 4800, 9600 and 19,200										
Data Interface		RS-232 bidi	rectional interfac				400, 4800, 9600	) and 19,200			
Pan Size				Circu	ular 4.5 inch diar	neter					
Operating Temperature	5°C to 40°C										
Relative Humidity	80 % for temperatures up to 31°C decreasing linearly to 50 % at 40°C										
Power Supply	Automatic switching 115/230 Volts, 50/60 Hz ± 10%										
Windscreen	Circular 6 inch diameter x 3.25 inches high										
Calibration Weight	150g	250g	350g	500g	1000g	1500g	400g	500g	2000g		
	100g	200g	200g		500g	1000g	200g	200g	1000g		
Housing (WxDxH)	7.5" x 11.25" x 3.25"										
Weight	~ 9.5 lbs										

# **Specifications for SL Laboratory Balances:**

Model	SL400	SL600	SL1000	SL2000	SL3000	SL5000	SL6000	SL3100D	SL5200D	
Weighing Mode	Single Range								Dual Range	
									(Floating Tare™)	
Capacity	400g	600g	1000g	2000g	3000g	5000g	6000g	1000g 3000g	2000g 5000g	
Readability	0.01g							0.01g 0.1g		
Tare Range	0-400g	0-600g	0-1000g	0-2000g	0-3000g	0-5000g	0-6000g	0-3000g 0-3000g	0-5000g 0-5000g	
Repeatability (Standard Deviation)	0.01g								0.01g 0.05g	
Linearity	±0.015g							±0.015g ±0.05g		
Stabilization Time	User Selectable									
Weighing Speed	Adaptive									
Display Update Interval					300 ms					
Data Interface	RS-232 bidirectional interface is standard. Baud rates are 300, 600, 1200, 2400, 4800, 9600 and 19,200									
Pan Size	Circular 4.5 inch diameter Circular 6.5 inch diameter									
Operating Temperature	5°C to 40°C									
Relative Humidity	80 % for temperature up to 31°C decreasing linearly to 50 % at 40°C									
Power Supply	Automatic switching 115/230 Volts, 50/60 Hz ± 10%									
Windscreen	Optional									
Calibration Weight	400g	600g	1000g	2000g	3000g	5000g	6000g	3000g	5000g	
	200g	500g	500g	1000g	2000g	2000g	5000g	2000g	2000g	
Housing (WxDxH)	7.5" x 11.25" x 3.25"									
Weight	~ 8.5 lbs									

Model	SG3000	SG5000	SG8000	SG12000	SE250	SE2500			
Weighing Mode	Single Range								
Capacity	3000g	5000g	8000g	12000g	250g	2500g			
Readability		0.	0.001g	0.01g					
Tare Range	0-3000g	0-5000g	0-8000g	0-12000g	0-250g	0-2500g			
Repeatability		0.	0.001g	0.01g					
(Standard Deviation)									
Linearity		±0.	± 0.0015g	± 0.015g					
Stabilization Time	~ 3 seconds								
Weighing Speed	Adaptive								
Display Update Interval	300 ms								
Data Interface	RS-232 bidirectional interface standard. Baud rates are 300, 600, 1200, 2400, 4800, 9600 and 19,200								
Pan Size		Rectangular	4.5" plus 2	4.5"					
			removable plastic						
Operating Temperature	5°C to 40°C								
Relative Humidity	80 % for temperatures up to 31°C decreasing linearly to 50 % at 40°C								
Power Supply	Automatic switching 115/230 Volts, 50/60 Hz ± 10%								
Windscreen		Not Av	7.5Wx8.25Dx9.5H	Optional					
Calibration Weight	3000g	5000g	8000g	10000g	250g	2500g			
	2000g	2000g	5000g	5000g	200g	2000g			
Housing (WxDxH)	7.5" x 11.25" x 3.25"								
Weight		~ 10	~ 9.0 lbs	~ 8.5 lbs					

# **Specifications for SG General Balances and SE Gem Balances:**

# Limited Warranty:

All Scientech Series 12000 Electronic Balances and their accessories are warranted against defects in materials and workmanship within North America for three (3) years and all other areas for two (2) years from the date of delivery. During the warranty period, Scientech will repair, or at its option replace at no charge, components that prove to be defective. The equipment must be returned, shipping prepaid, to Scientech's product service facility. This limited warranty does not apply if the equipment is damaged by accident or misuse or as a result of service or modification by other than a Scientech service facility. The foregoing warranty is in lieu of all other warranties expressed or implied including but not limited to any implied warranty of merchantability, fitness, or adequacy for any particular purpose or use. Scientech, Inc. shall not be liable for any special incidental or consequential damages whether in contract, tort or otherwise.

# **Extended Warranty:**

Extended warranty coverage can be purchased in a one or two year term at the time of balance purchase. Details are available by contacting Scientech at (800) 525-0522 or (303) 444-1361 or Fax (303) 444-9229 or E-mail inst@scientech-inc.com.

# **Returned Goods Procedure:**

Should it become necessary to return any item to Scientech for any reason, please contact our Product Service Department at (800) 525-0522 or (303) 444-1361 or Fax (303) 444-9229 or E-mail inst@scientech-inc.com. When you contact us, please be ready to provide the model number, serial number and a description of the problem. Frequently we can provide self-help information that will eliminate the need for returning the unit.

If equipment return is required, please pack the items in the original box and packing material. As an alternate, place equipment in a snug fitting box, then pack that box in a larger box with at least four inches of packing material between the two boxes. Scientech does not assume responsibility for underpacked items.

Please include the name and phone number of the person we should contact regarding repair question(s).

Normally, products are repaired and shipped within 5 working days after their arrival at the product service facility. This is an average time and could vary depending on the workload.


Shipping Address:

Scientech, Inc. 5649 Arapahoe Avenue Boulder, CO 80303 U.S.A.

# **Disposal of Electrical and Electronic Equipment:**


Scientech, Inc. recommends the following for disposal of electrical and electronic equipment:

- 1. The best option is to reuse the equipment in its entirety.
- 2. Where the equipment can not be reused in its entirety, priority should be given to reuse of its subassemblies and components.
- 3. Where reuse is not appropriate, electrical and electronic equipment, including batteries, should be recycled according to local ordinances.
- 4. Waste electrical and electronic equipment should never be mixed with municipal waste.




# **Quick Setup Guide:**

**1** UNPACK BALANCE



**3** LEVEL BALANCE

Adjust the FRONT FEET to level the balance by centering the LEVEL INDICATOR.




UNLOCK CLAMPING SCREW


 Remove the paper tag.
 Turn the knob, in the direction shown until finger tight. See page 4 of the manual.



ND STATIC ELECTRICITY









**7** WARM UP 1 HR, THEN CALIBRATE

Calibration instructions in manual.